## BULLETIN

From Atari Field Service



DATE August 30, 1983

# STARWARS

## The Following Items Require Your Immediate Attention!

### ATARI Color X-Y Monitor (STAR WARS\* only)

### High-Voltage Board

Change capacitors C3 and C4 from  $100 \,\mu\text{F}$  at 35 volts to  $220 \,\mu\text{F}$  at 35 volts, with a low Equivalent Series Resistance (ESR) Rating. The Atari part number is 123009-227. The following manufacturers' capacitors will work:

Illinois Capacitor Nichicon 227 RMR 050M (50 volts) UPA1V221M (35 volts)

#### Deflection Board

When servicing the Deflection board, please change diodes CR2 and CR11 to Type-1N4148, Atari part number 131033-001. The old diodes (Type-1N914) will open, causing fuses F1 and F2 to blow.

1983 Lucasfilm Ltd. & Atari, Inc. All rights reserved. Lucasfilm trademark used under license.

1105 N. Fair Oaks . Sunnyvale, California 94086 . (408) 745-2900 . (800) 538-1611